TEL: 82-53-668-0286 FAX: 82-53-668-0277

AFS: RKRRYNYX
E-mail: aisd@korea.kr
Web: https://aim.koca.go.kr

REPUBLIC OF KOREA

Ministry of Land, Infrastructure and Transport Office of Civil Aviation

11, Doum 6-ro, Sejong-si, 30103, Republic of Korea

AIP

Supplement 92/25

16 OCT 2025

GEN: NIL

ENR: NIL

A D: MUAN/Muan INTL(RKJB)

TEMPORARY SECURITY FENCE AND TEMPORARY OBSTACLES ERECTED

1. INTRODUCTION

Temporary security fence & lights and CCTVs will be installed on the area as follows.

2. PERIOD

From 1500 UTC 15 OCT 2025 To 1500 UTC 19 FEB 2026

3. OBST INFORMATION

NR.	OBST Type	Position	Height	
			AGL	AMSL
1	Security Fence	35°00'19.45"N 126°22'51.20"E	3.3 m	19.27 m
2	Security Fence	35°00'19.68"N 126°23'07.55"E		
3	Security Light	35°00'19.38"N 126°22'52.75"E	5.0 m	19.65 m
4	Security Light	35°00'19.40"N 126°22'54.53"E		
5	Security Light	35°00'19.45"N 126°22'58.17"E	5.0 m	20.97 m
6	Security Light	35°00'19.48"N 126°23'00.03"E		
7	Security Light	35°00'19.53"N 126°23'03.69"E	5.0 m	19.87 m
8	Security Light	35°00'19.56"N 126°23'05.51"E		
9	CCTV	35°00'19.36"N 126°22'51.34"E		
10	CCTV	35°00'19.43"N 126°22'56.30"E	7.0 m	22.40 m
11)	CCTV	35°00'19.51"N 126°23'01.88"E		

4. REMARKS

- (1) During working period, pilots should exercise caution and follow ATC's instruction.
- (2) Work by equipments & vehicles will be conducted in the area as shown in AIRAC AIP SUP 95/25 (CONSTRUCTION WORK FOR RUNWAY EXTENSION).
 - (Until the AIRAC AIP SUP 95/25 becomes effective, working area information will be provided by AIRAC AIP SUP 72/25.)
- (3) Temporary security fence & lights and CCTVs will be installed as shown in the diagram.
- (4) Temporary security fence & lights and CCTVs do not penetrate obstacle limitation surface.
- (5) Any change to the contents of these pages will be notified by NOTAM.

(AIP SUP 71/25 is hereby superseded)

5. DIAGRAM Displaced temporary Security Fence Displaced threshold 300.0m Security Fence Security Light REMARK CCTV 3~8