

TEL : 82-53-668-0286
FAX : 82-53-668-0277
AFS : RKRRYNYX
E-mail : aisd@korea.kr
Web : <https://aim.koca.go.kr>

REPUBLIC OF KOREA
Ministry of Land, Infrastructure and Transport
Office of Civil Aviation
11, Doum 6-ro, Sejong-si, 30103, Republic of Korea

AIRAC
AIP
Supplement 105/25
13 NOV 2025

GEN : NIL

ENR : NIL

A D : MUAN/Muan INTL(RKJB)

UNSERVICEABILITY OF ALS

(Effective : 1600UTC 24 DEC 2025)

1. INTRODUCTION

The ALS for RWY 01 at RKJB will be U/S due to WIP.

2. PERIOD

From 1600 UTC 24 DEC 2025 To 1600 UTC 19 FEB 2026

3. WORKING AREAS (See the diagrams below)


NR.	Position	
①	34°58'14"N	126°22'57"E
②	34°58'14"N	126°22'60"E
③	34°58'44"N	126°22'57"E
④	34°58'44"N	126°22'60"E

4. REMARKS

- (1) During working period, pilots should exercise caution and follow ATC's instruction.
- (2) Work by equipments & vehicles will be conducted in the area as shown in diagrams.
- (3) Any change to the contents of these pages will be notified by NOTAM.

(AIRAC AIP SUP 65/25 is hereby superseded)

5. DIAGRAMS



NR.	Position	
①	34°58'14"N	126°22'57"E
②	34°58'14"N	126°22'60"E
③	34°58'44"N	126°22'57"E
④	34°58'44"N	126°22'60"E

